

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2014 PETERBILT

Ad Number # 8146
Year: 2014
Location: Indiana
Manufacturer: Peterbilt Trucks
Model: 365
VIN: 1XPSPD9X1ED233163
Engine: Paccar MX
Horsepower:
Transmission: Eaton
Mileage: 110000
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8146>

Description

CALL MIKE BARRETT AT 317 281 1894 FOR ADDITIONAL DETAILS ON THIS SALVAGE TRUCK. Layover on right side. Known damage to hood, cab, DPF cover, fuel tank, interior, unknown damage to engine, front axle, radiator, DPF and under hood components. See photographs.

Additional Information

Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images

