

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

Honda Civic

Ad Number # 8174
Year: 2011
Location: Alabama
Manufacturer: Volvo Truck
Model: HVTECH
VIN: 20103
Engine: Chrysler
Horsepower:1.2
Transmission: Automatic
Mileage: 22
Hours: 2
ECM Mileage:13
ECM Hours:2
Running:
Inspected By:Vick



<http://afequip.nx.gg/view/listing/8174>

Description

fhdjlsdkjfsfjls

Additional Information

Physical Appearance	
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection	
Engine Appearance (Oil Leaks Present?)	Good Notes :-
Lights All Around Equipment Condition	Ok Notes :-
PAINT (ANY BODY DAMAGES OR SCRATCHES)	Ok Notes :-

Mechanical Detail	
Engine Starts Properly	Good Notes :-
Engine Accelerates and Cruises Properly/Smoothly	Ok Notes :-
Engine Noise Normal (Cold/Hot & High/Low Speeds)	Ok Notes :-

Images

