GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2008 CADDILLAC DTS

Ad Number # 8197

Year: 2008

Location: Pennsylvania **Manufacturer:** ------

Model: DTS

VIN: 1GKEE90Y28U550239

Engine: GMC **Horsepower:**

Transmission: Other

Mileage: 50000

Hours:

ECM Mileage:0 ECM Hours: Running: Inspected By:



http://afequip.nx.gg/view/listing/8197

Description

Call Vince at 317 938 2019 for details on this unit. Mileage = 48,867 Engine - V-8 Gas - Runs OK Trans - Automatic Battery - Good Brakes - Fair Tires - Fair Wheels - Alloy - Center caps missing Interior - Fair - Leather Seats, PS, AC, Power Windows & Locks, Tilt Wheel, Cruise Control, AM/FM CD Exterior - Fair - color is Silver Grey, Glass is good, minor scrapes & dents, no serious body damage Mileage = 46,777 Engine - V-8 Gas - Runs OK Trans - Automatic Battery - Good Brakes - Fair Tires - Fair Wheels - Alloy Interior - Fair - Leather Seats, PS, AC, Power Windows & Locks, Tilt Wheel, Cruise Control, AM/FM CD Exterior - Color is Black, Glass is OK. Rear taillight lense broken, minor scrapes & Dents, no serious body damage

Additional Information

Physical Appearance

AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Images











