GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2013 KOMATSU 930e UNIT 246

Ad Number # 8220 Year: 2013 Location: Naveda Manufacturer: Komatsu Equipment Model: 930e VIN: KMTHD038N61A31557 Engine: Cummins Horsepower: Transmission: NOT APPLICABLE Mileage: 17378 Hours: ECM Mileage:0 ECM Hours: Running: Inspected By:



http://afequip.nx.gg/view/listing/8220

Description

UNIT WILL NEED A NEW ENGINE. COMPLETE FAILURE. Some minor pieces were removed and will have to be replaced on the drive axle. Parts are the electric brake control valves as told to us.

Additional Information

Physical Appearance

AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images



Images

