## **GENERAL EQUIPMENT INSPECTION DETAILS**

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

#### 2012 Vermeer

**Ad Number #** 8224

**Year:** 2012

**Location:** Indiana **Manufacturer:** Vermeer

Model: D20X22II

VIN: 1VR6180T4C1000744 Engine: NON POWER UNIT

Horsepower:

Transmission: NOT APPLICABLE

Mileage: 835 Hours:

ECM Mileage:0 ECM Hours: Running: Inspected By:



http://afequip.nx.gg/view/listing/8224

#### Description

Hours: 835 Additional details available upon request Inspection completed by Vermeer May 2015 UNIT INCLUDES: MIXER UNIT MX 125 1VRXO300XC1002467 Machine ran good Items Checked: Oil level - ok Grease cup - ok Bolts for tightness - ok Battery cover - ok Hoses and ball valves – ok TRAILER - FT-20I VIN 5FTEE2326C1039650 Left rear taillight housing is dented Right fender dented Rt. Taillight and marker next to it are no good Spare rim missing tire Rt rear tire side wall is damaged, other 3 are good Overall Condition: Good

Additional Information

### **Physical Appearance**

AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

# Images

