## **GENERAL EQUIPMENT INSPECTION DETAILS**

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

## 2008 MCI J 4500

**Ad Number #** 8055

Year: 2008

Location: Indiana

Manufacturer: MCI Buses

**Model:** J 4500

VIN: 2M93JMHA38W064936

Engine: Detroit Horsepower:500 Transmission: Allison Mileage: 156930

Hours:

ECM Mileage:157211

ECM Hours: Running: Inspected By:



http://afequip.nx.gg/view/listing/8055

## Description

Great government off leases. Please call us today for further information and remaining warranty information.

Additional Information

Physical Appearance	
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection	
Engine Appearance (Oil Leaks Present?)	Good Notes :-
Lights All Around Equipment Condition	Good Notes :-
PAINT (ANY BODY DAMAGES OR SCRATCHES)	Good Notes :-
Mirrors Condition	Good Notes :-
Differential Appearance (Oil Leaks Present?)	Good Notes :-
Warning Buzzers Functioning	Good Notes :-
Tires or Tracks	Good Notes :-
Warning Lights	Good Notes :-
Interior Condition (Clean Dirty or Damaged)	Good Notes :-
Horn Operable	Not Apply Notes :-
Body Condition	Good Notes :-
Gauges Functioning	Good Notes :-
General Appearance of Equipment	Good Notes :-
Rear Axle Capacity	Good Notes :- 23000

Mechanical Detail	
Engine Starts and Runs	Good Notes :-
Drive Shaft and Yolks	Good Notes :-
Differentials and Fluids	Good Notes :-
Battery Condition	Good Notes :-

## Images

















