

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2007 International Bus

Ad Number # 8097
Year: 2007
Location: Indiana
Manufacturer: Shuttle Bus
Model: Eldorado Elite
VIN: 1HVBTAAL17H428146
Engine: International
Horsepower:220
Transmission: Allison
Mileage: 76000
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8097>

Description

Equipment located in Indiana. Great Running unit. Please call for details.

Additional Information

Physical Appearance	
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection	
Tires or Tracks	Good Notes :- New tires
Warning Lights	Good Notes :-
Body Condition	Good Notes :-

Mechanical Detail

Images

