

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2007 MCI J 4500

Ad Number # 8101

Year: 2007

Location: Indiana

Manufacturer: MCI Buses

Model: J4500

VIN: 2M93JMDA87W064256

Engine: Caterpillar

Horsepower:410

Transmission: ZF TRANSONIC

Mileage: 225922

Hours:

ECM Mileage:0

ECM Hours:

Running: 1

Inspected By:



<http://afequip.nx.gg/view/listing/8101>

Description

Please call 317 938 2019 for details and legal sale date.

Additional Information

Physical Appearance	
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection	
Tires or Tracks	Ok Notes :- 40 percent average thread life. Good for putting into service
Warning Lights	Good Notes :-
Body Condition	Good Notes :-
Front Axle Capacity	Ok Notes :- 16000
Rear Axle Capacity	Good Notes :- 23000

Mechanical Detail

Images

