

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2007 SETRA BUS

Ad Number # 8145
Year: 2007
Location: Indiana
Manufacturer: Setra Buses
Model: S417
VIN: WKKAA4CDX73000476
Engine: Detroit
Horsepower:500
Transmission: Allison
Mileage: 116000
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8145>

Description

Good running government owned and maintained buses. Buses are in good condition and will be sold in good clean condition. All mileages are very low. The units have good tires with about 50%. Please call Mike Barrett at 317 281 1894 for any details on these buses. WE HAVE EXCELLENT FINANCE PROGRAMS FOR GOOD CREDIT HOLDERS.

Additional Information

Physical Appearance	
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection	
Engine Appearance (Oil Leaks Present?)	Good Notes :- GOOD CONDITION
Lights All Around Equipment Condition	Good Notes :-
PAINT (ANY BODY DAMAGES OR SCRATCHES)	Good Notes :-
Mirrors Condition	Good Notes :-
Differential Appearance (Oil Leaks Present?)	Good Notes :-
Warning Buzzers Functioning	Good Notes :-
Tires or Tracks	Good Notes :-
Warning Lights	Good Notes :-
Interior Condition (Clean Dirty or Damaged)	Good Notes :-
Horn Operable	Good Notes :-
Bus Restroom Condition	Good Notes :-
Body Condition	Good Notes :-
Signal System Working Properly	Good Notes :-
Gauges Functioning	Good Notes :-
General Appearance of Equipment	Good Notes :-
Front Axle Capacity	Good Notes :- 16000

Physical Appearance	
Rear Axle Capacity	Good Notes :- 23000

Mechanical Detail	
Engine Starts and Runs	Good Notes :-
Brake Chamber Visual Condition	Good Notes :-
Air Line Visual Condition	Good Notes :-
Transmission Issues or Active Codes	Good Notes :-
Suspension Visual Condition	Good Notes :-
Steering Box Condition (oil leaks present?)	Good Notes :-
Drive Shaft and Yolks	Good Notes :-
Engine Belt Condition	Good Notes :-
Wheel Visual Condition	Good Notes :-
Brake Pad Visual Condition If Possible	Good Notes :-
Air Conditioning and Heating Performance	Good Notes :-
Transmission Diagnose Report Results	Good Notes :-
Differentials and Fluids	Good Notes :-
Battery Condition	Good Notes :-
Active Engine Codes	Good Notes :-
RADIATOR CONDITION	Good Notes :-

Images

