GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2006 MACK

Ad Number # 8149 Year: 2006 Location: Indiana Manufacturer: Mack Trucks Model: GRANITE 713 VIN: 1M2AG11C56M041087 Engine: Mack Horsepower:370 Transmission: Mack Transmission Mileage: 329998 Hours: ECM Mileage:0 ECM Hours: Running: Inspected By:



http://afequip.nx.gg/view/listing/8149

Description

Great running unit. This sale is for the cab and chassis. The roll off unit will be removed off of the truck.

Additional Information

| Physical Appearance AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection | |
|---|-----------------------|
| | |
| Lights All Around Equipment Condition | Ok Notes :- |
| PAINT (ANY BODY DAMAGES OR SCRATCHES) | Good Notes :- |
| Mirrors Condition | Ok Notes :- |
| Differential Appearance (Oil Leaks Present?) | Good Notes :- |
| Warning Buzzers Functioning | Ok Notes :- |
| Tires or Tracks | Not Apply Notes :- |
| Horn Operable | Good Notes :- |
| Signal System Working Properly | Ok Notes :- |
| Gauges Functioning | Ok Notes :- |
| General Appearance of Equipment | Good Notes :- |
| Windshield Wipers Condition and Performance | Ok Notes :- |
| Front Axle Capacity | Good Notes :- |
| Window Function Condition | Ok Notes :- |

| Mechanical Detail | |
|---|------------------|
| Engine Starts and Runs | Good Notes :- |
| Brake Chamber Visual Condition | Good Notes :- |
| Air Line Visual Condition | Good Notes :- |
| Transmission Issues or Active Codes | Good Notes :- |
| Steering Box Condition (oil leaks present?) | Good Notes :- |
| Drive Shaft and Yolks | Good Notes :- |
| Engine Belt Condition | Good Notes :- |
| Hose Condition | Good Notes :- |
| Wheel Visual Condition | Good Notes :- |
| Air Conditioning and Heating Performance | Good Notes :- |
| Transmission Diagnose Report Results | Good Notes :- |
| Battery Condition | Good Notes :- |
| Active Engine Codes | Good Notes :- |

Images

