

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2002 WESTERN STAR

Ad Number # 8153
Year: 2002
Location: New York
Manufacturer: Western Star Trucks
Model: 4900
VIN: 2WLPCD2G21K966757
Engine: Caterpillar
Horsepower:
Transmission:
Mileage: 31656
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8153>

Description

2002 Zimmerman 10YD Volumetric Concrete Mixer. This truck is in ok shape. It runs and drives. Truck has 46k rears and 20K fronts

Additional Information

Physical Appearance	
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection	
Engine Appearance (Oil Leaks Present?)	Ok Notes :-
Lights All Around Equipment Condition	Ok Notes :-
PAINT (ANY BODY DAMAGES OR SCRATCHES)	Ok Notes :-
Mirrors Condition	Ok Notes :-
Differential Appearance (Oil Leaks Present?)	Good Notes :-
Warning Buzzers Functioning	Ok Notes :-
Tires or Tracks	Ok Notes :-
Warning Lights	Ok Notes :-
Interior Condition (Clean Dirty or Damaged)	Ok Notes :-
Body Condition	Ok Notes :-
Signal System Working Properly	Ok Notes :-
Gauges Functioning	Ok Notes :-
General Appearance of Equipment	Ok Notes :-
Windshield Wipers Condition and Performance	Ok Notes :-
Window Function Condition	Ok Notes :-
Rear Axle Capacity	Ok Notes :- 46000 lbs

Mechanical Detail	
Engine Starts and Runs	Good Notes :-
Brake Chamber Visual Condition	Good Notes :-
Air Line Visual Condition	Good Notes :-
Steering Box Condition (oil leaks present?)	Good Notes :-
Drive Shaft and Yolks	Good Notes :-
Engine Belt Condition	Good Notes :-
Wheel Visual Condition	Good Notes :-
Brake Pad Visual Condition If Possible	Good Notes :-
Air Conditioning and Heating Performance	Good Notes :-
Boom or Bucket Hoist Cylinders Visual Condition	Good Notes :-

Images

