

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2003 VOLVO VHD ROLL OFF

Ad Number # 8154
Year: 2003
Location: California
Manufacturer: Volvo Truck
Model: VHD
VIN: 4V5KC9G603N350369
Engine: Volvo
Horsepower:365
Transmission: Eaton Autoshift
Mileage: 375000
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8154>

Description

Extremely clean lease trun in roll off. 4.33 Rear axle ratios. 20K fronts 46k Rears RTO16910AS2 Autoshift. Please call Vince at 317 938 2019 for more details on this unit.

Additional Information

Physical Appearance	
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection	
Engine Appearance (Oil Leaks Present?)	Good Notes :-
Lights All Around Equipment Condition	Good Notes :-
PAINT (ANY BODY DAMAGES OR SCRATCHES)	Good Notes :-
Mirrors Condition	Good Notes :-
Differential Appearance (Oil Leaks Present?)	Good Notes :-
Warning Buzzers Functioning	Good Notes :-
Tires or Tracks	Good Notes :-
Warning Lights	Good Notes :-
Interior Condition (Clean Dirty or Damaged)	Good Notes :-
Horn Operable	Good Notes :-
Body Condition	Good Notes :-
Signal System Working Properly	Good Notes :-
Gauges Functioning	Good Notes :-
General Appearance of Equipment	Good Notes :-
Windshield Wipers Condition and Performance	Good Notes :-
Window Function Condition	Good Notes :-

Physical Appearance	
Dump Hoist Condition	Good Notes :-

Mechanical Detail	
Engine Starts and Runs	Good Notes :-
Air Line Visual Condition	Good Notes :-
Steering Box Condition (oil leaks present?)	Good Notes :-
Air Conditioning and Heating Performance	Good Notes :-
RADIATOR CONDITION	Good Notes :-

Images

