GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

Hitachi EX5500

Ad Number # 8178

Year: 20011 Location: Naveda

Manufacturer: Hitachi Equipment

Model: EX 5500

VIN: HCM18N00K00001051

Engine: Other Horsepower:2500 Transmission: Other Mileage: 20028

Hours:

ECM Mileage:ECM MILEAGE NOT ACCURATE

ECM Hours: Running: Inspected By:



http://afequip.nx.gg/view/listing/8178

Description

Please call us at +1 317 938 2019 for details on this Hitachi front shovel. Machine is in good shape and is ready to be put in service. Spoke to Bruce at the factory for PIN: FF18N00001051 Engine: CN50C33184684 Model: 55006 Engine Model: _____ Base Machine: 3220F Comp. Warranty: NO Base Machine Code: Component Serial Numbers Build Codes Code Description Code Description 6860 LOADING SHOVEL BOOM 7280 LOADING SHOVEL ARM 8600 35.5 CU YD SHOVEL BUCKET

Additional Information

Physical Appearance

AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical D)etail
--------------	--------





















