

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2009 D 9T

Ad Number # 8180
Year: 2009
Location: Ohio
Manufacturer: Caterpillar
Model: D9T
VIN: CAT00D9TJRJS01331
Engine: Caterpillar
Horsepower:436
Transmission: Caterpillar Automatic
Mileage: 18821
Hours:
ECM Mileage:18821
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8180>

Description









Good running machine. This machine was working in a paper mill pushing sawdust. It is in good shape and needs very little attention. Please a call to Please call for details. 317 938 2019 WE SHIP WORLDWIDE. PLEASE CALL FOR DETAILS AND RATES.

Additional Information








Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images



Images



Images

