

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2009 DITCH WITCH R300 ZAHN

Ad Number # 8195
Year: 2009
Location: Texas
Manufacturer: Ditch Witch
Model: R300 ZAHN
VIN: CMWR300XT90000637
Engine: Caterpillar
Horsepower:
Transmission: Auto Shift
Mileage: 0
Hours:
ECM Mileage:0
ECM Hours:
Running: 1
Inspected By:



<http://afequip.nx.gg/view/listing/8195>

Description

Engine Type: Kohler Pro 30 Operational: Yes Starts Easily: Yes Engine Smoke: No Brakes Work Well: Yes Steers Correctly: Yes Paintwork Sound: Fair Shifts Properly: Yes Comments: Control valve leaking into exhaust. Digital hour readout does not seem to be working properly. Everything else seems to be functioning properly.

Additional Information

Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images

