

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2005 Peterbilt

Ad Number # 8213
Year: 2005
Location: Indiana
Manufacturer: Peterbilt Trucks
Model: 379 EXHD
VIN: 1XP5D49X85N856849
Engine: Cummins
Horsepower:500
Transmission: Eaton
Mileage: 750000
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8213>

Description

Great running Heavy haul truck. Heavy rears on 46k Rears. Call Vince at 317 938 2019 or Rick at 317 281 1894 for additional details.

Additional Information

Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images

