

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2011 MACK ROLLOFF

Ad Number # 8229
Year: 2011
Location: Indiana
Manufacturer: Mack Trucks
Model: GU 813
VIN: 1M2ZX13C9BM012294
Engine: Mack
Horsepower:
Transmission: Fuller
Mileage: 148425
Hours: HOURS 8763
ECM Mileage:
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8229>

Description

Great running units that are ready to be put into service. All are DOT ready and have been fleet maintained. Not any damages to any of the trucks that will exceed 500 dollars in retail repair value. Please call Vince at 317 938 2019 or Rick at 317 281 1894 for details.

Additional Information

Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images

