

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2012 MACK GRANITE TRI AXLE

Ad Number # 8234
Year: 2012
Location: New York
Manufacturer: Mack Trucks
Model: GRANITE
VIN: FLEET
Engine: Mack
Horsepower:
Transmission: Allison
Mileage: 50K TO 60K
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8234>

Description

Great running dump trucks. 20k Fronts 44k Rears. Mack MP8 and Allison Transmission. Electric tarp Vibrators 20k Drop Axle Allison Transmission

Additional Information

Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images

