GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2015 Kenworth

Ad Number # 8323 Year: 2015 Location: Indiana Manufacturer: Crane (Crawler) Model: Kenworth Manitex VIN: Engine: Cummins Horsepower: Transmission: Fuller Mileage: 0 Hours: ECM Mileage:0 ECM Hours: Running: Inspected By:Third Party



http://afequip.nx.gg/view/listing/8323

Description

2015 KENWORTH T800 CRANE TRUCK Cummins ISX/525hp w/engine brake, RTL0-18913A 13 speed transmission, 40,000# front axles, 69,000# rears on air ride suspension, lift axle, pusher axle, full locking rears, Manitex TC700 Cab Crane 70 ton, 115' crane, wireless remote control PTO, dual 75 gallon fuel tanks, four outriggers, 425/65R22.5 front floats, 11R22.5 rubber on all aluminum wheels, dual air breathers, power windows & locks, tilt/tele, cruise control, 296" w.b.

Additional Information

Physical Appearance

AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

