GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2011 Vermeer Navigator D20X22II Package

Ad Number # 8348

Year: 2011

Location: Indiana **Manufacturer:** Vermeer

Model: D20X22II VIN: MULTIPLEVINS Engine: Caterpillar Horsepower:

Transmission: NOT APPLICABLE

Mileage: 0 Hours:

ECM Mileage:0 ECM Hours: Running: Inspected By:



http://afequip.nx.gg/view/listing/8348

Description

1. Vermeer D20x22II Navigator Drill 1VR618OT2C1000743 2. DCI Model F2 Locator Package SN: F2R30013184 - 3. Vermeer MX125 Mix Tank SN: 1VRX030U3FC1002469 4. Roose Model RR 0 135 SN 1R9RP1110BP136196 5. McLaughlin Model V80DLE-HD410 SN: V8H111711664 6. Felling Model FT-201 Trailer SN 5FREE2327C1039656


Additional Information

Physical Appearance


AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Images LT. WI-112 MODEL NO. SERIAL NO. ORGENVILLE, SOUTH CAROLINA.

Images



Images



Images









