

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2006 RT 750E

Ad Number # 8363
Year: 2006
Location: Indiana
Manufacturer: Grove Equipment
Model: RT 750E
VIN: 224511
Engine: CumminsQSB 6.7L diesel
Horsepower:179KW
Transmission: Auto Shift
Mileage: NOT APPLICABLE
Hours:
ECM Mileage:NA
ECM Hours:NA
Running:
Inspected By:CHARLIE M



<http://afequip.nx.gg/view/listing/8363>

Description



OFF LEASE EQUIPMENT. This is a good machine that will pass any inspection. We had it taken back to the OEM dealer and brought up to specs before it was turned in. Please call Vince for more details at 317 938 2019 <http://speceps.com/spec/lifting-11169/grove/rt750e.html>

Additional Information

Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images



Images

