GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2016 Setra 216

Ad Number # 8387

Year: 2015

Location: Arizona

Manufacturer: SETRA BUSES

Model: 417

VIN: WKKA57XH2F3010216

Engine: Mercedes Horsepower:500 Transmission: Allison Mileage: 137853

Hours:

ECM Mileage:0 ECM Hours: Running: Inspected By:



http://afequip.nx.gg/view/listing/8387

Description

Extremely well maintained and clean units. On of the best operations in the bus business I have ever seen.

Additional Information

Physical Appearance

AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Images 6 350 KG (14 000 LBS) THIS VEHICLE CONFORMS TO ALL APF

Images







