

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

Celedon Trailers

Ad Number # 8420
Year: 2016
Location: Indiana
Manufacturer: Multiple Manufacturers and Units
Model: Various Models
VIN: VARIOUS
Engine: NON POWER UNIT
Horsepower: Not Applicable
Transmission: Not Applicable
Mileage: Not Applicable
Hours:
ECM Mileage: 0
ECM Hours:
Running:
Inspected By: Richard Freeman



<http://afequip.nx.gg/view/listing/8420>

Description

Various Caledon trailers. Inspected 9/10/18. Trailers are in good road worthy condition. Reefers that were powered up are in good condition. Inventory includes dry van and reefer units. Customer has taken very good care of this equipment. The items listed below are the ones that were present on the lot today. All equipment is in proper working condition to the best of our knowledge without further inspection. Year 2016 unit 257332 SR# 1JJV532DXG L900932 Year 2016 unit 400598 SR# 1GRAA0629GE701391 Year 2016 Reefer unit 400336 SR# 1GRAA0624GB706550 Year 2016 Reefer unit 400342 SR# 1GRAA0625GB706556 Year 2016 Reefer unit 400350 SR# 1GRAA0624GB706564 Year 2016 Reefer unit 400375 SR# 1GRAA0629GB706589 Year 2016 Reefer unit 400404 SR# 1GRAA0621GB706618 Year 2017 Unit 258669 SR# 1nVS32DXHL902634 Year 2016 Reefer Unit 400593 SR # 1GRAA0625GE701386 Year 2016 Reefer Unit 400376 SR# 1GRAA0625GB706590 Year 2016 Reefer Unit 400400 SR# 1GRAA0624GB706614 Year 2017 Unit 258817 SR# DJV532D3HL902782

Additional Information


Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images



Images



Images



A 4x6 grid of 24 images showing various views of white Celadon semi-trailers. The images include close-ups of tires, side views of the trailers, and details of the Celadon logo and identification tags. The trailers are parked in a lot, and the images show different angles and details of the vehicles, such as the front, side, and rear views, as well as close-ups of the tires and the Celadon logo. The images are arranged in a grid, with each image showing a different view or detail of the trailers.

Images

