

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

Prevost Bus

Ad Number # 8440
Year: 2007
Location: Indiana
Manufacturer: Prevost Buses
Model: H345
VIN:
Engine: Detroit
Horsepower:
Transmission: ZF TRANSONIC
Mileage: 701369
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8440>

Description


Bus is in starting running condition. Please contact us for details. It was put into our shop to have new batteries and get to running condition. The buses have some repairs needed to be in 100% running. We have successfully gotten them to running condition to drive.

Additional Information




Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images



Images



Images

