

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2006 FREIGHTLINER Rolloff

Ad Number # 8208
Year: 2006
Location: California
Manufacturer: Freightliner Trucks
Model: FL
VIN: 1FVHA6CK36PW94218
Engine: Detroit
Horsepower:
Transmission: Eaton
Mileage: 245622
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8208>

Description

Very good running offlease roll off unit. Unit is ready to be put into service. This is a double frame or heavy frame truck with 20k fronts and 46k rears. Call the serial number into FL for additional details. Mileage: 244082.6 Engine: Detroit Series 60 Tires: Good overall – No retreads Wheels: Steel Attachments: Roll Off AC, PS, AM-FM, CD Player, Cruise Control, Single Exhaust Starts under its own power and idle: Yes Moves through normal speed ranges in both forward & reverse with and without full load: Yes Steer right & left in both forward & reverse at designed turning radius: Yes Lift, lower & tilts normally with and without load No apparent fuel leaks No visible oil, water, fluid or hydraulic leaks. Engine operates without excessive exhaust smoke. All motors operate without arcing and/or sparking. Unit's attachments perform all of its required functions. Unit's horn, parking brake, service brake, lights, and all other safety equipment operational. No visible frame damage Tires fair/good Unit complete with all originally-installed parts or equivalents that are installed intact/undamaged. Sheet metal intact. (normal wear and tear) Call us at 317 938 2019 or 317 220 6982.

Additional Information

Physical Appearance

AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images

