

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2012 Vermeer

Ad Number # 8225
Year: 2012
Location: Indiana
Manufacturer: Vermeer
Model: D20X22II
VIN: 1VR6180T7C1000740
Engine: NON POWER UNIT
Horsepower:
Transmission: NOT APPLICABLE
Mileage: 841
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8225>

Description

Hours:841 Additional details upon request Vermeer Inspected July 2015 UNIT INCLUDES: MIXER UNIT MX 125 1VRX03U9C2002471 Unit in good working condition. Machine ran good Items Checked: Oil level - ok Grease cup - ok Bolts for tightness - ok Battery cover - ok Hoses and ball valves – ok FELLING MODEL FT20I DROP DECK TRAILER VIN 5FTEEE2323C1039654 ID CMB-0740 Overall Condition: Good ROOSE REEL CARRIER Model # RR-135 VIN 1R9RP1114BP136198 All lights work properly Tires in good condition Hydraulic pumps working Overall Condition: Good OCI Model FL LOCATOR PKG. - SN F2R30013181 Unit ID #CBM-0740 Auto Greaser Tether Remote Mobile Net

Additional Information

Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images

