

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2009 Kenworth

Ad Number # 8226
Year: 2009
Location: Indiana
Manufacturer: Kenworth Trucks
Model: T800
VIN: 1XKDD49X29J255452
Engine: Cummins
Horsepower:500
Transmission: Eaton
Mileage: 475000
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8226>

Description

Good running winch truck. Please call for additional details. Vin number analyze Entered VIN 1XKDD49X29J255452 Corrected VIN 1XKDD49X29J255452 Squish VIN 1XKDD49X9J WMI 1XK VIS identifier N/A VDS DD49X29J Year identifier 9 Serial number 255452 VIN type normal Check digit valid Check VIN number: 1XKDD49X29J255452 and learn more about the history of this vehicle. General Information Make Kenworth Model T800 Model year 2009 Trim level Construction Body style Conventional Cab Engine type 14.9L L6 6X4 Fuel type Diesel Vehicle class Truck Tractor Vehicle type Truck Assembly plant Chillicothe, Ohio Manufactured in United States Vehicle specification Body type Conventional Cab Displacement SI 14900 Displacement CID 909 Displacement Nominal 14.9 Engine type L6 Engine cylinders 6 Fuel type Diesel Driveline 6X4 GVWR range >30001

Additional Information

Physical Appearance

AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images

