

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2012 PROSTAR

Ad Number # 8238
Year: 2012
Location: Ohio
Manufacturer: International Truck
Model: PROSTAR
VIN: 546709
Engine: MaxxForce
Horsepower:
Transmission: Eaton
Mileage: 425000
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8238>

Description

Mileage - 421,758 Engine - Max Force 13 Diesel - Trans - Eaton 10 Speed Batteries - Good Brakes - Fair Suspension - Air ride tag axle Front Axle - 12000 lbs Rear Axle - 23000 lbs Tires - 60% - 2 rear tires flat Wheels - Aluminum Interior - Fair - PS, AC, AM/FM Radio Exterior - Color is White - Raised roof sleeper, glass is ok, minor scrapes & dents, no serious body damage This truck has a single axle rear with a tag axle to make it a tandem. It is a 4X2 tractor.

Additional Information

Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images

