

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2013 PETERBILT 389

Ad Number # 8279
Year: 2013
Location: Texas
Manufacturer: Peterbilt Trucks
Model: 389
VIN: 1XPXDP9X0DD176622
Engine: Paccar
Horsepower:
Transmission: Fuller
Mileage: 112000
Hours:
ECM Mileage: 112000
ECM Hours:
Running:
Inspected By: VINCE



<http://afequip.nx.gg/view/listing/8279>

Description

Mileage = 111,800 Good running truck. Please call Vince for Details. Engine - Paccar 12.9 Litre diesel - runs ok Trans - 13 speed Batteries - Fair Brakes - Fair Tires - Poor - all need to be replaced Wheels - Aluminum Interior - good - needs cleaning - PS, AC, Power windows & Locks Exterior - Good - windshield chipped, other glass ok, Paint is white, minor scrapes & dents, no serious body damage

Additional Information

Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images

