

GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

2012 PETERBILT 365 With SUPER SUCKER

Ad Number # 8313
Year: 2012
Location: Texas
Manufacturer: Peterbilt Trucks
Model: 385
VIN:
Engine: Cummins
Horsepower:385
Transmission: Eaton
Mileage: 50000
Hours:
ECM Mileage:0
ECM Hours:
Running:
Inspected By:



<http://afequip.nx.gg/view/listing/8313>

Description



This unit is in good working condition. It was inspected by the manufacturer and very little was needed to this unit. It is a unit that can be put to work. They have noted a minor leak in an upper hydraulic cylinder. Please call for details Make Peterbilt Model Year 2012 Model 365 Engine Manufacturer Cummins Engine Series ISX11.9 Engine Capacity L6, 11.9L Fuel Type Diesel Vehicle Type Air-Braked Vehicle Chassis Truck Chassis Drive Line Type Truck 6x4

Additional Information

Physical Appearance
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

Mechanical Detail

Images



Images

