

# GENERAL EQUIPMENT INSPECTION DETAILS

This is an inspection that is completed by a contracted agency and represents a visual inspection of this equipment or property. Agency is not responsible for hidden damages or mechanical failures in the future of this equipment as this is a visual inspection. This inspection is completed without any warranty from the inspection. Whether it be "Expressed or Implied" This inspection report will follow with illustrations of the equipment and the written form of what we are able to visually inspect. By accepting this inspection or estimate you are agreeing indemnify, defend, save and hold harmless the the providing company of this repair/estimate, its agents and employees from all liabilities, charges, expenses and costs on account of or by reason of any such injuries, deaths, liabilities, claims, suits or losses however occurring or damages growing out of the same.

## 2011 International 8600

**Ad Number #** 8332  
**Year:** 2011  
**Location:** Indiana  
**Manufacturer:** International Truck  
**Model:** 8600  
**VIN:**  
**Engine:** International  
**Horsepower:**410  
**Transmission:** Eaton  
**Mileage:** 517250  
**Hours:**  
**ECM Mileage:**0  
**ECM Hours:**  
**Running:**  
**Inspected By:**



<http://afequip.nx.gg/view/listing/8332>

### Description

International Maxiforce 13 410 HP Engine Brake 517,249 Miles Eaton Fuller Auto Transmission 170" Wheelbase 12,000 lb. Front Axle 40,000 lb. Rears Air Ride Suspension Air Ride Cab Sliding 5th Wheel Sun Visor, Air Conditioning, Cruise Control, Power Windows, Power Locks, Power Mirrors, Heated Mirrors, Dual High Back Seats, Tilt Steering Wheel All Aluminum 22.5 Wheels Dual Aluminum Tanks

### Additional Information

<b>Physical Appearance</b>
AFEquip.com is not responsible for hidden damages or mechanical failures as this is only a visual inspection

**Mechanical Detail**

## Images

